# Weathertzanton Assistance Program

## Work Order (Bid Form)

### **WORK ORDER INFORMATION**

Work Order Name: 14014SO2340Work Order Type: WeatherizationAudit Name: 14014SO2340

#### **CLIENT INFORMATION**

Client Name: 14014SO2340 Address: , Unit 1420

Client ID: 14014SO2340 Columbia, TN 38401

Alt. Client ID: Maury

#### **CLIENT CONTACT INFORMATION**

14014SO2340 Applicant/Person of Record

#### <u>AGENCY INFORMATION</u>

Agency:South Central Human Resource AgencyAgency Phone:(931) 433-7182Address:1437 Winchester HighwayFax:(931) 438-0074

Fayetteville, TN 37334 *Email Address:* 

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

Older mobile home w/ addition. Replace HVAC system. AC doesn't work.

Client Name: 14014SO2340 Client ID: 14014SO2340 Alt. Client ID: Maury Work Order (Bid Form)
Work Order Name: 14014SO2340
Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 6

	Measure	1	Gene	eral Ai	r Sealir	ng				Com	poner	its					Inspe	ected
Comment 1. Install 1 interior storm window (6x18) in Bed#1 Shower.  2. Re-galze wood windows &caulk to air seal.  3. Repair bellyboard insulation.  4. Repair ductwork and mastic registers.  5. Mastic return air plenum.  6. Clear caulk around fireplace in addition.  7. Install baseboard in addition and caulk to seal.  8. Repair holes in walls.  9. Clear caulk jambs & casings.  10. Install consumer education provided elect. insulators & caulk around boxes.  11. Caulk around bathtub & repair hole behind washer.  12. Repair wall in bed#3's closet and ceiling.  13. Seal old dryer vent  14. Repair floor in DWH compartment & caulk to air seal.																		
		,-	r. Nep	all 1100	יייווו טייי	i i comp	artirio	SIIL OX C	auin it		stimate	d			,	Actual		
#	Material /	La	bor	Descri	ption / C	omment		Units	Qty	Uni	t Cost	Tota	al .	Qty	U	Init Cost	To	otal
1	Miscellan Supplies	eo	us	Infiltra	tion Red	duction		Each	1									
2	Labor			Labor				Hour	6									
(	Other Detai	ı							1	<b>-</b>					7			
L																		
г									Measu	re Sub	Total:				Sur	b Total:		
	Field Note	s:																

	Replace HVAC System			Componen	ts HVAC	•		Inspecte
Comment				Estimated	,		Actual	
# Material / Labo	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Heating Equipment	HVAC	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						1		
			M	a Sub Tatali		]	Sub Total:	
			weasur	e Sub Total:		'	Sub Total.	
Measure 3 I	nstall digital thermostat			Componen		;		Inspecte
Comment	_			Estimated			Actual	
Comment # Material / Labo	r Description / Comment	Units	Qty	•		Qty		Inspecte
Comment	_	<i>Units</i> Each	<b>Qty</b> 1	Estimated			Actual	
Comment  # Material / Labo  1 Heating Equipment	r Description / Comment			Estimated			Actual	
Comment  # Material / Labo  1 Heating	r Description / Comment Digital termostat	Each	1	Estimated			Actual	
Comment  # Material / Labo  1 Heating Equipment  2 Labor	r Description / Comment Digital termostat	Each	1	Estimated			Actual	
Comment  # Material / Labo  1 Heating Equipment  2 Labor	r Description / Comment Digital termostat	Hour	1	Estimated		Qty	Actual	
# Material / Labo  Heating Equipment  Labor  Other Detail	r Description / Comment Digital termostat	Hour	1	Estimated Unit Cost		Qty	Actual Unit Cost	
Comment  # Material / Labo  1 Heating Equipment  2 Labor	r Description / Comment Digital termostat	Hour	1	Estimated Unit Cost		Qty	Actual Unit Cost	

Measure 4 DWI			Inspected					
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Pipe and Tank Insulation	Each	1					
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	DWH Pipe and Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
-	lace Front Door Unit, V		ock	Componen	<i>ts</i> Door			Inspected
<b>Comment</b> replace	with manufactured door	ſ		Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors	Replace Front Door Unit, WS, DS, Lock	Each	1					
2 Labor	Labor	Hour	1					
Other Detail				,	,		,	
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Client Name: 14014SO2340 Client ID: 14014SO2340 Alt. Client ID: Maury Work Order (Bid Form)
Work Order Name: 14014SO2340

Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0 Page 4 of 6

nated  ost Total  ostal:	Sub Total:
otal:	Sub Total:
	′H <i>Inspect</i>
onents DWF	Actual
ost Total	Qty Unit Cost Total
otal:	Sub Total:
itai.	
ub To	ub Total:

1	Measure 8 Smo	ke/ CO2 Detector Com	ıbo		Componen	its H&S			Inspected	
C	omment									
				Estimated	<del></del>	Actual				
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	Smoke/CO2 Detector Combo	Each	1						
2	Labor	Labor	Hour	1						
C	Other Detail						] [			
				Measur	e Sub Total:			Sub Total:		
Г	Field Notes:				L			L		
		or Barrier Needed ement/Crawlspace)			Componer	nts H&S			Inspected	
					Estimated	1		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	Basement / crawlspace vapor barrier	Each	1						
2	Labor	Labor	Hour	1						
C	Other Detail				1		] [			
				Measur	e Sub Total:		,	Sub Total:		
	Field Notes:									
			Work Or	der Gra	and Total:		Gran	d Total:		

Client Name: 14014SO2340 Client ID: 14014SO2340 Alt. Client ID: Maury

Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0 Page 6 of 6